

## Wind Chill Temperature Factor

Knots	Meters/Sec.	Air Temperature											
		25	20	15	10	5	0	-5	-10	-15	-20	-25	-30
0.0	0.0	25	20	15	10	5	0	-5	-10	-15	-20	-25	-30
		Felt Temperature											
5.0	2.5	25	19	14	9	3	-2	-7	-12	-17	-23	-28	-33
9.0	4.5	22	16	10	4	-2	-8	-14	-20	-26	-32	-36	-44
13.0	7.0	21	15	8	2	-4	-11	-18	-25	-32	-38	-45	-52
19.0	9.5	21	14	7	0	-7	-14	-21	-29	-36	-43	-50	-57
24.0	12.5	21	13	5	-2	-9	-17	-24	-32	-39	-47	-54	-61
30.0	15.5 #	20	13	5	-3	-11	-18	-26	-34	-42	-49	-57	-65
37.0	19.0	20	12	4	-4	-11	-19	-27	-35	-43	-51	-59	-68
44.0	22.5	20	12	4	-4	-12	-20	-28	-36	-44	-52	-60	-69

**Notes:**

# Upper limit of safe crane operation.

- 21 degrees is the temperature for frozen meat in cold storage